





Hellga Company

Commode 1200 - C

1 Search the packing for elements according to the number
















② Search for reinforcement




















③ Follow the dimension










	Follow the dimension			
	X mm	Y mm	Z mm	
1	832	360	18	pcs 2
2	732	360	18	pcs 1
3	1200	380	18	pcs 1
4	1160	360	18	pcs 1
5	762	340	18	pcs 1
6	1160	80	18	pcs 2
7	756	387	18	pcs 2
8	410	410	18	pcs 1
9	410	170	18	pcs 2
10	350	100	18	pcs 4
11	318	100	18	pcs 2
12	405	764	3	pcs 1
13	787	764	3	pcs 1
14	354	355	3	pcs 2















				
10	5	2	4	12
V	D	P	O	K

